



TOGETHER
for a sustainable future

OCCASION

This publication has been made available to the public on the occasion of the 50th anniversary of the United Nations Industrial Development Organisation.



TOGETHER
for a sustainable future

DISCLAIMER

This document has been produced without formal United Nations editing. The designations employed and the presentation of the material in this document do not imply the expression of any opinion whatsoever on the part of the Secretariat of the United Nations Industrial Development Organization (UNIDO) concerning the legal status of any country, territory, city or area or of its authorities, or concerning the delimitation of its frontiers or boundaries, or its economic system or degree of development. Designations such as “developed”, “industrialized” and “developing” are intended for statistical convenience and do not necessarily express a judgment about the stage reached by a particular country or area in the development process. Mention of firm names or commercial products does not constitute an endorsement by UNIDO.

FAIR USE POLICY

Any part of this publication may be quoted and referenced for educational and research purposes without additional permission from UNIDO. However, those who make use of quoting and referencing this publication are requested to follow the Fair Use Policy of giving due credit to UNIDO.

CONTACT

Please contact publications@unido.org for further information concerning UNIDO publications.

For more information about UNIDO, please visit us at www.unido.org



09097



Distr.
LIMITED

ID/WG.303/3
26 July 1979

ENGLISH

United Nations Industrial Development Organization

Technical Consultation on Corrosion
in Fertilizer Plants

Sandviken, Sweden, 27 - 31 August 1979

001197

COUNTRY PAPER FROM INDIA

STRESS CORROSION FAILURES IN REFORMER FURNACE COMPONENTS*

by

C.V. Srinivasan **

* The views expressed in this paper are those of the author and do not necessarily reflect the views of the secretariat of UNIDO. This document has been reproduced without formal editing.

** Senior Inspection Engineer, Madras Fertilizers Limited, Madras, India.

id.79-5871

SUMMARY

The present article describes the repeated and unusual occurrences of stress corrosion failures at the top inlet material components of the primary reformer furnace in an Ammonia Plant. Experience in repair and remedial actions to reduce such incidence of failure is also discussed in this paper.

INTRODUCTION

Madras Fertilizers Limited, India, operates a 750 MT/day Ammonia Plant. Catalytic reforming of steam hydrocarbon mixture is the process adopted for the manufacture of ammonia. The reformer furnace is of Halder Topsoe (Denmark) design and has two radiant side-fired furnaces. The steam naphtha mixtures are passed thru vertically kept reformer tubes inside the reformer furnace.

Each reformer furnace has 120 reformer tubes - 6" ODx18/16" thick. The reformer tubes are fed from inlet headers thru inlet pigtaile and the reformed gas leaves thru outlet pigtaile connected to bottom collectors. Steam-naphtha mixture (4.5:1) enters the reformer tubes at 35 kg/cm² and 450°C.

Reformer furnaces require heat resistant high alloy castings and wrought nickel-chromium alloys. Centrifugally cast heat resistant alloy HK 40 is one of the most widely used material for the reformer tubes operating upto 950°C. The reformer tubes in Madras Fertilizers Ltd. are made of centrifugally cast HK 40 alloy (25 Cr, 20 Ni, 0.4% C). This material has excellent creep rupture properties, good corrosion resistance against attack by furnace gases, and a definite economic advantage over similar wrought iron-chromium-nickel alloys.

In our case the reformer tube terminates, at the top, in a HK-40 stub-end. The stub-end has a loose carbon steel flange which is bolted to the inlet hair-pin tube (fig. 1) The inlet hair pin tube extended, in the original arrangement, about 18" inside the reformer tube. The inlet pig-tails and reformer top stub-ends are outside the reformer furnace roof.

HISTORY OF FAILURES

In 1974, after 3 years of operation, during pressure testing after new catalyst loading, we observed leaks in some of the reformer tube top stub-end welds. Subsequent inspection revealed extensive cracking both longitudinal and circumferential-in the reformer tube stub ends (HK-40) and inlet pigtail (SS 321) weld cap welds. Such cracking in reformer furnace components is considered unusual although similar instances of failures have been experienced in a few steam-naphtha reforming furnaces elsewhere, in mid '60s and early '70.

Detailed metallurgical examinations were done on the cracked reformer tube stub end (HK 40) and inlet pigtail (SS 321). The failed stub end and inlet pigtail weld cap exhibited both transgranular and intergranular mode of cracking (fig. 2 and 3). Both the longitudinal (transverse) and the circumferential cracks originated at the inside surface and at the heat affected zone (HAZ) of the parent materials. Many of the longitudinal cracks extended to both sides of the weld. The circumferential cracks originated at the interface of the top weld layer and HAZ at the I. D., and propagated to the top layer of weld in the transverse (thickness) direction.

Predominant transgranular cracking in both the reformer tube stub-end and inlet pigtail weld-cap led to the conclusion that failure was by stress corrosion cracking. Presence of intergranular cracking observed along with transgranular cracks suggested that both chloride and caustic stress corrosion cracking could be the mechanism for the massive failures. Small traces of chloride and alkali present in the steam entering the reformer furnace was considered the possible source of corrodent. Residual weld stress was also the cause for both longitudinal (transverse) and circumferential cracking.

Repair welding of used reformer components is often considered difficult because of the micro-structural changes associated with high temperature operation and also because these changes make it difficult to adopt the same original manufacturing welding procedure. In our case, repair welding was done using high nickel-chromium filler wire and electrodes (Inconel 82 and Inconel 182). Most of the cracked HK 40 stubends were replaced with

Inconel-600 (72 Ni., 16 Cr., 7 Fe.) alloy because of its known resistance to chloride stress corrosion cracking and also due to its ready availability.

In 1976, after 21 months of operation since repair welding and replacing most of the reformer tube stub ends with Inconel-600, we experienced a similar cracking problem in both the HK-40 tube HAZ and the inlet pigtail weld cap. Repeated condensation, concentration of high temperature chloride and/or caustic, in the empty zones above the reformer furnace was considered the mechanism of the stress corrosion failures. To overcome this, the inlet pigtail arrangement was modified.

A notable exception, in the 1976 failure, was that the Inconel-600 stub ends did not develop any cracking. We, therefore, replaced all the remaining HK-40 stub-ends with Inconel-600 adopting the same repair weld procedure done in 1974.

In January 1978 - 14 months after replacing the stub ends in all 240 tubes with Inconel-600 and modifying the inlet pigtail assemblies, we experienced a similar large scale longitudinal and circumferential stress corrosion cracking. This cracking, however, was significantly different from the previous failures and was found mostly in the high nickel Inconel 600 stubs only. Stress corrosion cracking by high temperature caustics and high left-over weld stress was considered the mechanism for the Inconel 600 stub end failures.

CORRECTIVE MEASURES

Having experienced three similar failures in 4 years with different materials and design modifications to the top inlet reformer components, we considered several proposals to prevent this occurrence.

Several questions which arose were:-

- i. How to prevent contact of welded HK 40 and Inconel-600 from high temperature chlorides and or caustics present in steam and what methods would be realistic and economically justifiable.
- ii. Would stress relieving of the top stub end welds (between used HK-40 tube and Inconel-600/HK-40 stubs) considerably bring down the residual stresses and reduce the chances of stress corrosion cracking and if so what are the practical difficulties in performing a high temperature stress relieve annealing.
- iii. Would lowering the concentration of the corrodents by process improvements reduce the risk of such failures.
- iv. Would any other preventive method against direct impingement of the corrodents in the weld zones be possible and the relative success of such method.

On careful examination of these alternatives, stress relieving the weld areas held out much promise and was adopted.

High nickel-chromium-iron or iron-chromium-nickel alloys are not routinely subjected to thermal stress relief as a part of the manufacturing procedure. Insufficient service data on the success of such stress relieved HK-40 and Inconel alloys in reformer service and the practical difficulties involved in the heat treatment discouraged us from attempting this alternative during

the earlier failures. However, in January 1978, we experimentally stress-relieved some welds of HK-40 and Inconel 600 at 870°C and installed these in service. These experimentally stress-relieved repair welds did not develop any cracking in seven months exposure when inspected in September 1978, whereas the as repaired welds developed stress cracks similar to the three earlier failures (1974 - 78).

Having identified the role of residual weld stresses in the severity of the cracking, we experimentally studied and evaluated the effects of various heat treatment and welding parameters. Figures 4 and 5 show the yield stress vs. temperature curves for cast HK-40 and Inconel-82-filler wire. Inconel-82 values are similar to Inconel-600. From these curves, it is clear that Inconel-600 alloy has higher yield strength than HK-40. For our design temperature (450°C), the residual weld stress may become approximately 36,000 psi (2530 kg/sq.cm) for HK-40 and approximately 45,000 psi (3760 kg/sq.cm) for Inconel-600.

X-ray stress analysis was done to know the effect of heat treatment for different heating and cooling cycles. Maximum relief in residual stresses was attained when heat treated at 980°C with slow cooling. We also estimated the residual stresses in the machined edge of the tubes prior to welding. To our surprise, the machining stresses due to grinding, cutting, turning were found to be as high as 40% of the yield stress of the materials. In order to safeguard against possible chances of introducing excessive machining stresses, the machined tube ends were also mill-annealed at 980°C prior to welding.

From our experience high nickel alloys like Inconel 600 (72 Ni, 16 Cr) did not have a significantly higher stress corrosion resistance against attack by elevated temperature caustics. Therefore, in September 1978 when we had to replace the stub ends as the old ones had become short due to repeated cutting and rewelding we reverted to HK-40 stub ends. The weld zone on the catalyst tube was heat treated at 980°C prior to welding and again after completion of the welding. The part replaced tubes are in service for over ten months.

CONCLUSION

The repeated stress corrosion failures experienced at the inlet material portions of the reformer tubes in MFL Ammonia plant and the extent and severity of such cracking are unusual in the history of reformer operating plants in and outside India. Considerable experience has been gained from these failures and the subsequent metallurgical studies. High residual weld stress at the stub end weld region was identified as primarily responsible for the stress cracking. Repeated repairs accelerated the time-to-failure rate. Heat treatment of the stub end weld zones to mill-anneal temperature (980°C) is practical and would considerably bring down the residual stresses. The residual stresses will be less than 20% of the yield stress. This appears to be an effective method of reducing the incidence of stress corrosion failures in future.




FIG. 1. CATALYST TUBE STUB END



Fig 2(a)

Tangential section near the ID surface, showing transgranular cracks in the HAZ adjacent to the weld at the stub end (HK 40).

X 400




Fig 2(b)

Tangential section near the ID surface of the stub end. Cracks predominantly intergranular.

X 200



Figure 3 (a)
Intergranular cracking in sensitized Inconel-alloy 300
Steant : Glyceragia + Acetic Acid

BOOK






Figure 3 (b)
Intergranular and transgranular cracking in BK 40 catalyst tube.
Photo of longitudinal cracks. Steant:Glyceragia+Acetic Acid.

BOOK



We suggest that it is more likely that the original
manuscript was written in the 17th century
and that the present copy is a later transcription.
The handwriting is very good and the text is
well preserved. It was used for preparing the master copy.

C-626



81.10.21