



**TOGETHER**  
*for a sustainable future*

## OCCASION

This publication has been made available to the public on the occasion of the 50<sup>th</sup> anniversary of the United Nations Industrial Development Organisation.



**TOGETHER**  
*for a sustainable future*

## DISCLAIMER

This document has been produced without formal United Nations editing. The designations employed and the presentation of the material in this document do not imply the expression of any opinion whatsoever on the part of the Secretariat of the United Nations Industrial Development Organization (UNIDO) concerning the legal status of any country, territory, city or area or of its authorities, or concerning the delimitation of its frontiers or boundaries, or its economic system or degree of development. Designations such as “developed”, “industrialized” and “developing” are intended for statistical convenience and do not necessarily express a judgment about the stage reached by a particular country or area in the development process. Mention of firm names or commercial products does not constitute an endorsement by UNIDO.

## FAIR USE POLICY

Any part of this publication may be quoted and referenced for educational and research purposes without additional permission from UNIDO. However, those who make use of quoting and referencing this publication are requested to follow the Fair Use Policy of giving due credit to UNIDO.

## CONTACT


Please contact [publications@unido.org](mailto:publications@unido.org) for further information concerning UNIDO publications.

For more information about UNIDO, please visit us at [www.unido.org](http://www.unido.org)

We regret that some of the pages in the microfiche copy of this report may not be up to the proper legibility standards even though the best possible copy was used in preparing the master fiche.



08982



United Nations Industrial Development Organization

Distr.  
LIMITED  
ID/WG.303/1  
23 July 1979  
ENGLISH

Technical Consultation on Corrosion  
in Fertilizer Plants

Sandviken, Sweden, 27-31 August 1979


COUNTRY PAPER BY MAURITIUS  
CORROSION PROBLEMS ENCOUNTERED AT THE  
MAURITIUS CHEMICAL AND FERTILIZER INDUSTRY\*

by

Germain Comarmond\*\*

\* The views expressed in this paper are those of the author and do not necessarily reflect the views of the secretariat of UNIDO. This document has been reproduced without formal editing.

\*\* Ag. Technical Manager, The Mauritius Chemical and Fertilizer Industry Ltd.,  
Chaussée Tromelin, Fort George, Port Louis, Mauritius



## CORROSION PROBLEMS: MCFI CASE STUDY

Corrosion problems encountered at MCFI and relevant to this seminar are described below.

### A. NITRIC ACID PLANT

The Ammonia Oxidation Process (AOP) plant makes use of the high-pressure, mono-stage Dupont Process (see flow diagram).

#### (a) Tail Gas Reheater

##### (i) Description & Operation

At MCFI the reaction train (converter and tail gas reheater) is constructed as one integrated unit using Type 321 Stainless Steel (18/8).

The reheater portion utilises a vertical U-tube design as shown in Fig 1. With this design, there is a significant thermal gradient across the tubesheet which is thought to have led to continual tubesheet cracking.

The thermal gradient results when tail gas from the absorption column at 40°C, preheated to 90°C by steam in the tail gas tempering heater and to 150°C by process gas inside the preheater and further heated through the outerjacket of the tail gas is channelled out into the bottom header at 250°C. The resulting thermal gradient is quite steep ( $T = 650 - 250 = 400^\circ\text{C}$ ) on the cold side of the tubesheet and nearly the same across the pass-plate ( $T = 340^\circ\text{C}$ ).

##### (ii) Corrosion Problem

Stresses developed by these thermal gradients are believed to cause cracking of the tubesheet across tube ligaments (see photographs).

Furthermore, frequent start-ups and shutdowns of the nitric acid plant submit the tube plate to severe alternating stresses with high tensional and compressional forces.

Heating up and cooling down curves illustrate the problem (curves (a) & (b)): after the catalyst is lit, the plant is on line in about 30 minutes. (curve A). On shutdown, cooling to normal temperature is achieved in about 60 minutes, but with a steep temperature gradient at the beginning. (curve B).

It has been claimed that the problem of cracked tubesheets has been solved successfully by insulating the cold inlet to the reheater tube bundle with an acid resistant refractory to decrease the thermal gradient and by reducing the tubesheet thickness to reduce stresses.

After the cracking of the original 2" tubesheet (October 1976), the latter was reduced to 1½" and insulation placed at the cold inlet in a new equipment. But again cracking occurred (August 78), this time on the hot side where the temperature gradient is not significant (500°C). Another 1½" tubesheet, without insulation on cold side, also experienced cracking on the hot side (May 79).

(iii) Comments

Stresses due to thermal gradients provide only a partial explanation of the cracking of tubesheets. It appears that we are probably in presence of CORROSION FATIGUE. Adding to the stresses developed by the thermal gradient are severe alternating stresses at start-ups and shutdowns. Furthermore, the equipment undergoes stresses in a corrosive medium (NO<sub>x</sub> gases, nitric acid) and under a small pressure difference of 2 Kg/cm<sup>2</sup> which is the pressure drop of process gas across the system.

Indeed, at S/U but mainly during S/D, there is acid condensation inside the system. Blowing the system with hot air causes "revaporization" of this acid. Especially, on emergency shutdowns (for example caused by power failures) when the air compressor trips, blowing of the system after some time (after power is restored) causes acid vaporization at the tube plate. Power failures or power dips occur frequently in Mauritius.

No satisfactory solution has been found to this problem of cracked tubesheets and the reheater has now been replaced three times at MCFI. Being given that no modifications can be brought to the design, except for minor details, and that "tripping" conditions are bound to repeat themselves, it seems that the solution lies in the choice of a suitable material for the tubesheet which will better support the alternating stresses\* and thus extend the lifetime of the reheater. Otherwise, the existing tubesheet could probably be protected inside/outside by overlay welding of strip steel.

Suggestions are most welcomed.

\* It should be noted, however, that in order to reduce alternating stresses at S/U & S/D, the plant is now brought on line in 90 minutes (instead of 30 minutes) by gradually increasing the amount of reaction and at shutdown, reaction is slowly decreased to avoid sudden cooling.

(b) Tail gas Tempering Heater

(i) Description & Operation

This vertical shell and tube heat exchanger is intended to preheat tail gas from the absorption column from 40°C to 90°C before admission into the preheater where it is further heated to 160°C. Steam at 15 Kg/cm<sup>2</sup> and 202°C circulates inside the carbon steel shell and tail gas in the S.S 304L tubes (Fig 2).

(ii) Corrosion Problem

At the vicinity of the steam inlet to the exchanger, the tube metal temperature is hot enough to boil off droplets of acid carried over from the absorption column and the mist separator. This results in severe corrosion of the tubes at the inlet, immediately at the backface of the tubesheet. Leaking tubes at the top of the tempering heater have caused severe damage to the carbon steel shell which has been eaten up by the acid spray. (see photograph).

(iii) Solution

The tubes protrude through the bottom tubesheet in order to protect the tube plate and welds from any remaining acid droplet at the outlet.

It has been suggested that Teflon sleeves could be used to protect the tubes at the inlet of the heat exchanger to move the area of corrosion so that the tubesheet could be reused when the unit must be retubed. The damaged unit at MCFI has been replaced by a new one, where the 304L tubes have been replaced by SANDVIK 3RE60. SANDVIK 3RE60 - which is ferritic austenitic - is somewhat less resistant to acid and oxidising medium than austenitic steel 304L and problems are expected to crop up in the near future.

SANDVIK 2RE10, which is reported to be more resistant under similar operating conditions, would have probably been a much better choice.

(c) Cooler Condensers

(i) Description & Operation

In the cooler condenser, hot process acid gases are cooled on the tube side prior to absorption in the absorption column from 195°C to 40°C with chemically treated cooling water on the shell side. Shell side material is carbon steel; the tube bundle and tubesheet are made of S.S. Type 430.

(ii) Corrosion Problem

Usually, this type of condenser undergoes severe corrosion at the hot tube inlets just past the tubesheet in a region where condensed-acid formation and revaporization is believed to occur.

This does not appear to be the case at MCFI where inlet gases are at relatively moderate temperatures (185°C) compared to 300-315°C in other types of process.





However, 21 tubes out of 295 had to be plugged on one condenser due to leakages. A few tubes were extracted for inspection and found to be badly corroded at the extreme end where the tubes fit into the tubesheet. The tubes were found to be brand new with their full thickness all along their length.

(iii) Comments

The type of corrosion in this case can be best described as CREVICE CORROSION. Badly expanded tubes into the tubesheet allowed for crevices which were slowly replenished with the inhibitive chemical used from water treatment.

No further problems arose with this equipment; what happened should be imputed to bad workmanship.





B. AMMONIA STORAGE AREA

The ammonia storage facility at MCFI is designed to store 10,000 MT of liquid ammonia at atmospheric pressure.

Liquid ammonia offloaded from ships is stored in the tank at  $-33^{\circ}\text{C}$  ( $-28^{\circ}\text{F}$ ) and atmospheric pressure.

As the pressure in the tank tends to increase, due to heat gain from the tank's surroundings, the ammonia vapour is withdrawn, compressed in two-stages, condensed and returned in the storage tank.

When required, liquid ammonia from the storage tank is admitted into the transfer pumps which transfer ammonia to the ammonia burn tanks via the Ammonia Heater.

(a) The Ammonia Heater (and Ammonia Condenser)

(i) Description & Operation

The ammonia heater is a horizontal shell and tube heat exchanger with a removable U-tube bundle. Cooling water on the shell side is used to heat liquid ammonia from the storage tank to  $16^{\circ}\text{C}$  before admission in the Burn Tank.

The shell material is carbon steel A-106 "Gr B" and the tubes are constructed from carbon steel ASTM A179.

(ii) Corrosion Problem

The outside of the tubes, in contact with cooling water, have undergone heavy pitting at localized spots causing tubes to leak badly. The pitting occurred under sediment deposits on the tubes.

The Ammonia Heater is situated at the end of the cooling water loop where the pressure drop is a maximum. Furthermore, a large number of baffles closely-spaced increase the resistance to water flow. Consequently, the designed water velocity inside the heater is not attained.

Raw water at MCFI is filtered in a gravity sand filter. When both AOP and NPK plants are on, it may happen that the filter is not able to cope with the water requirements of both plants. (make-up to compensate blow-down). Water is then by-passed directly into the Cooling Tower. The result is that settlement of solid materials occur in the cooling system especially at spots where the required velocity is not achieved, causing severe pitting.

The same type of corrosion is experienced with the Ammonia condenser where cooling water on tube side is used to condense ammonia vapours from the second stage of compression on the shell side. Construction material is carbon steel ASTM A285 Gr C for the shell and ASTM A179 for the tubes.

Corrosion is most probably due to some electro-chemical action perhaps coupled with microbiological action favoured by the slow replenishment of oxygen under the deposits. Presence of anaerobic bacteria has been detected.

(iii) Solutions

Since it is believed that the muddy deposits are responsible for corrosion in this area, a mixed-media pressure filter has been ordered to replace the gravity sand filter.

Meanwhile, the ammonia heater tube bundle is removed every three months for cleaning. This preventive action has doubled the life time of the tube bundle which confirms the noxious action of deposits.


As regards the Ammonia condenser, when the pressure differential across the heater is higher than expected, the tubes are flushed by hosing with high pressure water in order to remove the sediments.

(b) Miscellaneous Problems

Other corrosion problems in this area result from rusting.

Being given the low temperature of liquid ammonia, there is ice-formation wherever valves or piping are not properly insulated. Dry ice would not be a problem. But during shutdowns the ice melts and the wet surfaces undergo heavy rusting. Problems are further aggravated by the proximity of the sea.


However, these problems are more relevant to the choice of proper protective coatings than of materials.




Cracked tube sheet of Tail Gas Reheater




Tail Gas Tempering Heater: Holed Shell



Cracked tube sheet of Tail Gas Reheater




Cracked tube sheet of Tail Gas Reheater



AMMONIA FROM SHIP

# SECTION 1




**FLOW DIAGRAM  
AMMONIA SECTION**

(Values in kg are Gauge Pressure)

**SECTION 2**

AMMONIA TRANSFER PUMPS  
ME-11-0050  
A & B



Notes: CONVERTER PANEL

1. Pressure Gauges: PIC 140  
PIC 141

2. Temperature Gauges: TR 169  
TIS 176  
TIS 174  
TR 178  
TR 176  
TR 177-178

3. Oil Cooler: C.W. In: TI 25  
C.W. Out: TI 33-34


○ PRESSURE GAUGES

⊙ TEMPERATURE GAUGES

NIT

SECTION 1






FLOW DIAGRAM  
 NITRIC ACID PLANT  
 (180 ST/D  $\text{HNO}_3$ )  
 165 MT

SECTION 2

**A-151**



**80.04.23**