



TOGETHER
for a sustainable future

OCCASION

This publication has been made available to the public on the occasion of the 50th anniversary of the United Nations Industrial Development Organisation.



TOGETHER
for a sustainable future

DISCLAIMER

This document has been produced without formal United Nations editing. The designations employed and the presentation of the material in this document do not imply the expression of any opinion whatsoever on the part of the Secretariat of the United Nations Industrial Development Organization (UNIDO) concerning the legal status of any country, territory, city or area or of its authorities, or concerning the delimitation of its frontiers or boundaries, or its economic system or degree of development. Designations such as “developed”, “industrialized” and “developing” are intended for statistical convenience and do not necessarily express a judgment about the stage reached by a particular country or area in the development process. Mention of firm names or commercial products does not constitute an endorsement by UNIDO.

FAIR USE POLICY

Any part of this publication may be quoted and referenced for educational and research purposes without additional permission from UNIDO. However, those who make use of quoting and referencing this publication are requested to follow the Fair Use Policy of giving due credit to UNIDO.

CONTACT

Please contact publications@unido.org for further information concerning UNIDO publications.

For more information about UNIDO, please visit us at www.unido.org

22719

SAFETY INSPECTION REPORT

CFC - Phase out project

Report No.:
Uniw0503/BUR/BRU

Final Version Vol. 02

Division
Electrical Engineering
Test Laboratory Vienna
A-1230 Vienna
Deutschstraße 10
Tel.: +43 1/610 91-0
Fax: DW 6505
eMail: pzw@tuev.or.at

Division Manager:
DI F. BITTERMANN
DW 6400
eMail: bm@tuev.or.at

Head Office
Krugerstrasse 16
A-1015 Vienna/Austria
Tel. +43.1.514 07-0
Fax +43.1.514 07-6005
<http://www.tuev.or.at>

Manufacturer: MOVALLED HOME APPLIANCES CO.



Factory Location:
Inspection dates:

Saveh, IRAN
14.10.1998

Accredited Testing
Laboratory,
Inspection Body,
Certification Body,
Calibration Body

Notified Body 0408

ISSUE: 18. January 2002

Head Office
A-1015 Vienna/Austria
Krugerstrasse 16
Tel. +43.1.514 07-0
Fax +43.1.514 07-6005
e-mail office@tuev.or.at

ACCREDITED TESTING AND CALIBRATION LABORATORY,
INSPECTION AND CERTIFICATION BODY
NOTIFIED BODY ID-NUMBER 0408

Branch Offices in
Dornbirn, Graz,
Innsbruck, Klagenfurt,
Lauterach, Linz,
Mattersburg, Salzburg,
St. Pölten, Wels and
Vienna

Subsidiaries in
Athens, Budapest,
Munich, Prague,
Ravenna, Teheran and
Vienna

Bank Accounts:
CA 0066-28978/00
BA 220-101-949/00
PSK 7072.756

1 Abstract

According to the definitions of the contract No. 98/184 a safety inspection of the converted plant using cyclopentane as blowing agent should guarantee the correct implementation and installation of safety procedures and systems. This inspection should be based on international standards and documented in a safety inspection report.

The scope of the inspections is specified in clause 4 of the „terms of reference“ from 18 June 1998.

For that purpose an inspection visit was executed on 14. October 1998 on the production site of Movalled in Saveh. The results of this inspection are stated in detail in the following report. Faults and deviations to the applicable international standards are listed related to the main areas and systems. Under the term „corrective action“ the possibilities to eliminate each inadequacy or incompleteness are mentioned.

Most of the machinery and equipment in Movalled is supplied by Cannon, Italy. The storage tank and the distribution piping to the mixing units is produced by locally companies. The production equipment consists of an underground storage tank (single wall) inside of a concrete basin, an partially underground and aboveground distribution piping and one premixing and mixing unit in a separate building. The foaming process shall be performed in two safety boxes, a cabinet foaming area and a second area for the foaming of doors and internal elements.

The production lines (preheating, drying, conveyor lines) should have been adapted from the former existing systems. The conversion of the production to the usage of flammable liquids required some adaptations or the shut-down of the existing non-explosion protected devices during foaming process.

At the inspection dates some principal installations and most of the main supplies have not been finished. Due to the fact, that all necessary supplies have not been connected, calibration gases and a lot of installations have not been completed at inspection date, there has been no possibility to perform the functional tests of safety relevant systems and components.

In order to issue a positive safety report the deviations had to be fixed, the missing installations had to be completed and the functional tests had to be performed.

During several missions to Iran, UNIDO's Project Manager has had the opportunity to check the plant site and confirmed (acc. to UNIDO-FAX dated 01-12-04 / 14:38:40) that all corrective actions required in this report have been taken care of and completed by the contractor (CANNON) and the local counterpart (MOVALLED).

A final inspection by the inspection body of TUV Austria to verify the proper correction of all deviations mentioned in our draft report Uniw0376/BUR/BRU, Vol. 1, has not been executed, therefore all results are based on the information of UNIDO (as mentioned above).

Note: A list of all deviations as collected during the inspection visit in 1998, an inspection protocol and a measurement protocol is provided with the draft report, Vol. 1!

1 ABSTRACT	2
<hr/>	
2 INTRODUCTION	5
2.1 GENERAL TEST PROCEDURES	5
2.2 SCOPE OF INSPECTIONS	5
2.3 DESCRIPTION OF ASSESSMENT RESULTS	5
2.4 ABBREVIATION LIST	6
3 SAFETY RELEVANT SYSTEMS	6
<hr/>	
3.1 EXPLOSION PROTECTION	6
3.1.1 ARTIFICIAL VENTILATION SYSTEM	6
3.1.2 NITROGEN BLANKETING (INERTIZATION) SYSTEM	8
3.1.3 GAS MONITORING SYSTEM	9
3.2 SAFETY CONTROL PANEL - EMERGENCY SHUT-DOWN SYSTEM	9
3.3 FIRE PROTECTION	10
4 STORAGE AREA FOR CYCLOPENTANE	11
<hr/>	
4.1 STORAGE TANK	11
4.2 FILLING (LOADING) STATION	12
5 C5-DISTRIBUTION PIPING SYSTEM TO PREMIX AREA	13
<hr/>	
6 PREMIX AREA	14
<hr/>	
6.1 PREMIXING UNITS (TYPE: A SYSPBTWIN 100 + PEF No. 290883)	14
7 CABINET FOAMING AREA	15
<hr/>	
8 DOOR (AND INTERNAL ELEMENTS) FOAMING AREA	17
<hr/>	

9 GENERAL CLAUSES

9.1	ELECTRICAL INSTALLATION	18
9.2	GROUNDING SYSTEM - POTENTIAL BONDING	19

10 SAFETY REQUIREMENTS DURING OPERATION OF THE PLANT

10.1	SAFETY INSTRUCTIONS	19
10.2	PERIODIC SURVEILLANCE	20
10.3	PREVENTIVE MAINTENANCE	20

11 CONCLUSIONS

12 INSPECTED PROJECT DOCUMENTATION

12.1	DOCUMENTATION OF THE SUPPLIERS EQUIPMENT (CANNON)	21
12.1.1	DRAWINGS	21
12.1.2	MANUALS	21
12.2	DOCUMENTATION OF MOVALLED	21

13 STANDARD LIST (INTERNATIONAL, EUROPEAN AND NATIONAL)

2 INTRODUCTION

2.1 General test procedures

All inspections and tests mentioned in this report are carried out in the same manner:

- A) Theoretical check of planning documents, certificates, schedules etc.
- B) Practical tests (visual inspection and/or measurements)
- C) Verification of test results according to international standards

2.2 Scope of inspections

The tests are performed in order to make a safety certification of the new installed refrigerator production plant possible. Therefore the safety relevant aspects of each part of the production line has to be carefully inspected and the safe function has to be verified.

The parts of the production line(s) under surveillance during the safety inspection are:

- A) General safety relevant systems
- B) Storage facilities for cyclopentane (storage tank, filling station etc.)
- C) C5-distribution piping to premix area
- D) Premix area
- E) Cabinet foaming area (safety box)
- F) Door and internal elements foaming area (safety box)

2.3 Description of Assessment results

For any clause of this report there is provided first a brief description of the existing equipment and a requirement list for all deviations existing at the inspection date in 1998.

Referring to the latest information of UNIDO (Dez. 2001), all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

The results of measurements and a list of basically international standards are mentioned in the final clauses of the report.

As there could no national regulations for the handling and storage of cyclopentane be provided by the recipient company, relevant technical rules and the engineering standard of developed countries was taken under consideration for the assessment of the safe design and function of the converted refrigeration plant.

2.4 Abbreviation list

C5	Cyclopentane
O ₂	Oxygen
N ₂	Nitrogen
LEL	Lower Explosion Limit
app.	Approximately
ESD	Emergency Shut Down
EEx d	Explosion protection type „flameproof enclosures - d“
EEx e	Explosion protection type „Increased safety - e“
EEx i	Explosion protection type „intrinsic safety - i“

3 Safety relevant systems

Safety relevant systems in general shall provide a suitable degree of protection against all dangers which can occur from the handling and storage of an easy flammable liquid (cyclopentane). This includes a safe design under consideration of the hazards of fire, explosion and leakage's.

3.1 Explosion protection

GENERAL DESCRIPTION:

The explosion protection system is based on primary and secondary protection equipment. Primary protection is the prevention of the occurrence of potentially explosive atmospheres by means of ventilation and inertization in endangered areas. A secondary explosion protection system is the detection of explosible atmospheres and the shut down of ignition sources when reaching the second alarm level of 30 % of the lower explosion limit (LEL).

Where the limitation of the concentration of an explosible gas mixture is not secured or an electrical device has to work in an explosion endangered area (zone 0, 1 or 2), the device must be properly explosionproofed for the degree of danger. The minimum degree for zone 1 is explosion group IIA and temperature class T2.

3.1.1 Artificial Ventilation system

DESCRIPTION:

A global artificial ventilation system is provided with local ducts for the foaming area inside the safety box and the housing of the premixing / polyol-cyclopentane day storage tank. There are redundant ventilation motors (no climbing opportunity, therefore the nominal air flow rate could not be checked) provided.

The air suction points are installed near the bottom of the housings (C5-gases and vapours are heavier than the air at ambient temperatures).

According to the documentation the air exchange rate should be calculated to keep the C5/air-mixture in the safety boxes below 15 % LEL. The dimension of the safety boxes were exceeding the calculated size, consequently the calculation had to be repeated and corrected.

The boxes shall be flushed automatically a minimum of 5 times before energizing the electrical equipment and starting of the production process. When the gas concentration exceeds the limit of 15 % LEL (second level alarm) the second fan is switched on. The ventilation system shall continue operation when the first level alarm (30 % LEL) is active. Therefore the ventilation system (e.g. fans) has to be anti-sparking.

For the function detection of the ventilation system a differential pressure switch should have been installed. In case of a failure of the ventilation system the electrical supply in the ventilated areas is switched off.

The exhausted air shall be conveyed outside the building through a chimney with a side-opening above the roof.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

- a) No calculation of the air exchange for the safety boxes available.

Corrective action:

providing of calculation documents for each safety box, adapted on the actual size of the box.

- b) Mounting of the ventilation ducts and differential pressure switch not finished.

Corrective action:

proper mounting of ventilation ducts and pressure switch.

- c) Lightning protection system for chimney is missing.

Corrective action:

Installation of a lightning rod or lightning rods or a metal frame beside/above the chimney (approximately 1 m distance and 1 m higher than the chimney). The lightning rods shall not be placed in the direction of the exhaust opening (app. 1 m against exhaust direction) and shall be properly mounted and connected to the steel construction of the building which fulfills the function of a lightning protection system.

- d) In case of a failure in the electrical supply no automatic emergency supply is provided.

Corrective action:

Installation of an automatic stand-by generator or changing of an existing generator from manual to automatic switch on.

e) The electrical supply is not connected.

Corrective action:

Completion of electrical installation.

f) The function and effectiveness of the artificial ventilation system could not be tested.

Corrective action:

After finishing of the installation and connection of the electrical supply the correct function can be tested.

g) A declaration or certification of the antisparking characteristic (according to VDMA 24169 or an equivalent standard) for the fans is not available.

Corrective action:

A corresponding manufacturer declaration or test certificate has to be provided.

3.1.2 Nitrogen blanketing (inertization) system

DESCRIPTION:

The system of nitrogen blanketing is used in order to reduce the amount of oxygen in a gas/air-mixture below the critical point for inertization, where no ignition of the mixture can take place because of the lack of oxygen (11,6 % O₂).

The nitrogen is provided by a compressor and N₂-Generator arranged in a separate building and stored in an accumulator intermediate tank. There is a separate nitrogen pipe provided for the storage tank.

The blanketing system is used in the refrigeration plant

- before the filling of the storage tank,
- for the inertization of the C5/polyol - day storage tank (monitored by pressure switch)
- and for the cabinet jigs injected shortly before the pouring through the mixing head (minimum amount of nitrogen is monitored by a flow meter and a timing system).

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

a) The nitrogen piping inside of the building is not ready installed.

Corrective action:

The piping should be properly installed and jointed.

3.1.3 Gas monitoring system

DESCRIPTION:

1 Gas detector shall be installed inside the premix area close to the mixer, further gas detectors shall be mounted in a sufficient amount inside the safety boxes (below the jigs close to the release openings and the first conveyor motor, on points of minimum air-suction).

The gas monitoring system is a SENTOX 96 type with an uninterruptible battery emergency supply.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

- a) The position of the sensors has been discussed. The gas detectors are not mounted. There is no calibration gas on site.

Corrective action:

The gas detectors must be mounted on the defined positions before commissioning and the calibration of the sensors has to be checked with a proper calibration kit (gases and flow meter).

3.2 Safety control panel - emergency shut-down system

DESCRIPTION:

The safety control panel is positioned outside the safety boxes (positioned close to the cabinet foaming area) and controls the ventilation system and the gas monitoring system.

The electrical supply of the premixing areas and inside of the safety boxes is switched off automatically and immediately in case of a first level alarm.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

- a) The electrical supply is not connected, no functional test possible.

Corrective action:

Completion of electrical installation and execution of the tests of safety functions during the next inspection visit.

- b) Emergency-shut-down switches near the door of the safety boxes are not mounted

Corrective action:

Mounting of the ESD-switches.

3.3 Fire protection

DESCRIPTION:

The company shall provide a sufficient fire extinguishing system close to endangered areas for the first and enhanced aid with hand-operated powder extinguishers on easy accessible position and a trained personal. To guarantee the efficiency of fire fighting a sufficient water supply and a fire brigade with foam for flammable liquids is necessary (company or local fire brigade). An emergency plan designed in case of fire shall be established.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

- a) The fire extinguishing system for the first aid is missing.

Corrective action:

There should be easy accessible powder extinguishers with at least 20 kg powder situated by the tank storage area, one fire extinguisher close to the premixing unit and one close to the each of the two foaming areas (safety boxes).

- b) A sufficient supply with foam or equivalent means of fire extinguishing for flammable liquids is not provided.

Corrective action:

The local fire brigade can be contacted to be prepared for the possible amount of flammable liquids in case of a fire alarm.

- c) There is no emergency plan in case of a fire alarm provided.

Corrective action:

Creation of a fire alarm plan for accidents inside and outside the factory building.

4 Storage area for cyclopentane

4.1 Storage tank

DESCRIPTION:

The storage tank is a 25000 l single wall steel tank arranged underground in a basin made of concrete. A weather-roof has been missing and the control panel has been located in a nearby (10 m distance from the storage tank) erected building without any sight to the filling and storage area. The grounding system for the tank is finished. The piping, the level switch and the electrical cables have not been finally connected.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

- a) The design, production, quality and test documentation of the storage tank is not complete.

Corrective action:

The company shall provide the following documentation:

- technical design criteria (e.g. calculation, materials, welding),
- internal process and quality verification data by the manufacturer (e.g. statistical tests, x-ray, destructible tests,
- welding data, certification of welding personal,
- test reports/certificates (e.g. hydrostatic pressure tests, complete tests on site)

- b) A leak detection in the basin (under the lowest point of the tank) is missing, a waterproof test of the basin is not documented.

Corrective action:

In order to guarantee an international safety standard, a single wall underground tank can only be approved if additional precautions are taken. The concrete basin can be accepted as a second safety measurement only when it is waterproofed and there is a leak detection system provided. Therefore a leak detector for dropping liquid must be installed (in a drop pan) under the lowest point of the tank. An acoustic alarm shall be generated when a leaking liquid is detected.

- c) The weather roof of the tank is not mounted and connected to the grounding system.

Corrective action:

Erection of a weather roof and connection to the grounding system. The sun protection roof shall (if necessary) consider the storage area for the filling container.

- d) The resistance of the grounding system is sufficient;
the measured values: 0,4 Ohms
are lower than the allowed maximum value of 10 Ohms.

No Corrective action!

- e) Classification, documentation and marking of hazardous areas is missing (ex-zones, safety zone)

Corrective action:

A drawing of the tank and filling area should be provided with the relevant dangerous areas marked (e.g. 1,5 m around exhaust openings of tank zone 1; 5 m around exhaust openings zone 2; inside the tank zone 1; a 5m zone around the storage tank and the filling station as safety zone (non-smoking, no storage of flammable materials, ...)).

The border of the safety zone and the area should be easily visible marked with a fire danger and no smoking sign.

- f) The piping installation and the electrical installation is not finished.

Corrective action:

Completion of the piping and installation.

4.2 Filling (loading) station

DESCRIPTION:

No filling station has been designed. There has been no equipment for the filling of the tank and no adequate documentation available.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

a) Corrective action:

A defined filling station for a intermediate storage container or drum shall be provided with a waterproof drop basin for the storage of dropping cyclopentane during filling operation (ca. 200 - 300 l). If necessary (demand of supplier of C5), a sunroof shall protect the whole filling area. A clamping system for the connection of the grounding system with the storage container must be installed. The filling pump must be suitable for cyclopentane and for the use in explosible atmospheres (ex-zone 1). The filling velocity of the cyclopentane has to be limited according to the diameter of the filling piping to reduce electrostatic charging of the flammable liquid itself. A maximum filling speed of 3m/sec is sufficient anyway.

The flexible pipe connections to the storage tank has to be electrostatic conductible.

5 C5-Distribution Piping system to premix area

DESCRIPTION:

The distribution piping of cyclopentane is a welded steel piping arranged partially underground inside a ditch made of reinforced concrete, partially aboveground to the premixing building. The underground ditch shall be filled with sand and covered with waterproof sealed concrete plates. In the same ditch there is the nitrogen-piping and the electrical cables. The C5-piping had no corrosion protection and has not been separated from the electrical cables. The aboveground piping has not been protected against direct lightning impact and not been thermal insulated. No ESD-fire-safe-valve has been installed. Inside of the building the distribution piping has not been finally mounted.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

a) The design, production and test documentation of the C5-piping is not complete.

Corrective action:

The company shall provide the following documentation:

- technical design criteria (e.g. design pressure, material, welding),
- welding data, certification of welding personal,
- test report (e.g. x-ray, pressure test on site before commissioning)

b) The protection and separation of the piping is not sufficient

Corrective action:

Underground part of piping: The piping should be cleaned (e.g. sandblasted) and coated against corrosion (e.g. with bitumen or polyethylen taping). It should not have a low resistance contact to the mounting iron construction (hazard of contact-corrosion). The electrical cabling should be installed either in a conduit system, inside of a metal cable tray or be separated in a minimum distance of 30 cm to the C5-piping.

Aboveground part of piping: The piping should be cleaned and coated against corrosion and thermal insulated. It should be covered by a metal roof against direct lightning impact. The electrical cabling should be installed in a conduit system or inside of a metal cable tray.

c) The ESD-fire-shut-down-valve on the entry of the building is not installed. The function could not be verified.

Corrective action:

Installation, functional connection and test of the ESD-valve.

6 Premix area

6.1 Premixing units (Type: A SYSPBTWIN 100 + PEF No. 290883)

DESCRIPTION:

The premixing units are arranged outside of the production hall in a separate building. The parts and devices involved with pure C5 and with C5/polyol blend are installed in a box, separated from other devices by walls and closed (monitored) doors. The box is connected with the artificial ventilation system and a gas sensor is mounted near by the mixing unit to monitor flammable vapours.

The bottom of the box is a basin to collect fluids in case of maintenance or accidents.

Inside the box is:

- the C5 metering and C5/polyol mixing unit with C5 piping, piston metering of C5, static mixer to mix C5 and polyol and delivery line for the blend to the dosing unit tank;
- the C5/polyol mixture tank (nitrogen blanketed) with working- and supermax level switches, temperature transducer, minimum pressure switch, stirrer, a water jacket with electrical heating devices and safety valves;
- the C5/polyol metering system with mixture pump.

The electrical parts in direct contact with C5 are in EEx i version.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

- a) The new position of the units is not marked in the documentation (general layout).

Corrective action:

The changed position in a separate building shall be completed in the general layout drawings.

- b) The gas detector is not mounted.

Corrective action:

The gas sensor have to be mounted before commissioning.

- c) The marking of intrinsically safe circuits (EEx i) is not sufficient.

Corrective action:

Intrinsically safe circuits shall be marked to separate them from non intrinsically safe circuits.

The marking can either be a light blue color of the cables or be made by signs or characters.

d) System descriptions of intrinsically safe circuits (EEx i) according to EN 50039 is missing.

Corrective action:

A system description of the intrinsically safe circuits (installed Ex-devices, cable length) have to be provided.

e) A connection of the skid to the main grounding system is missing.

Corrective action:

The metal skids have to be connected to the main grounding system (spring-washers).

f) The overload protection for internal transformers (T120 and T620) is missing.

Corrective action:

The overload protection must be double checked in accordance to the technical data of the transformers.

7 Cabinet Foaming Area

DESCRIPTION:

The foaming area for the cabinets is situated inside a separate safety box, which at the inspection date has been used for the refrigerator production with old production machines using CFC and had to be modified before startup of the new system. There should be one new foaming head provided for the cabinet foaming. The cabinets have been preheated and dried on one side of the safety box by infrared lamps without any mechanical protection. The cabinet jigs are moved automatically with conveyors to the foaming and heating devices. The new installation in the safety box has not been complete. A documented time cycle of the production could not be provided.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

a) The gas detectors are not mounted.

Corrective action:

The gas detectors must be mounted on the positions defined during the visit before commissioning and the calibration of the sensors has to be checked with a proper calibration kit (gases and flow meter). The area between the release of vapour and the conveyor motors and the infrared lamps has to be monitored by gas sensors. If this is not possible, all non-explosionproofed apparatus must be switched off for at least 90 seconds after the foaming shot.

- b) The equipotential grounding system is not installed.

Corrective action:

All metal parts (e.g. grid, ventilation ducts, ...) are to be connected to the grounding system inside the box (spring-washers).

- c) The preheating devices (infrared lamps) are not mechanical protected.

Corrective action:

A (grounded) metal mesh around the heating panel shall protect the lamps against any mechanical damage.

- d) The endangered area could not be clearly defined due to the missing time cycle of the foaming and heating process.

Corrective action:

A definition of the minimum time cycle for the foaming process has to be provided.

- e) There are non-explosionproofed flexible electrical plugs situated inside the safety box.

Corrective action:

All plugs have to be removed from the foaming area or electrically disconnected (cut off by failsafe timer system) during and 90 seconds after the foaming process.

- f) Several new devices are not installed (e.g. mixing head)

Corrective action:

All missing installation shall be completed before a final inspection.

- g) An ESD-switch and an escape route light close to the safety box door are missing.

Corrective action:

Mounting of the ESD-switch and connecting with the safety control panel. Mounting of the emergency route light (uninterruptible energy supply) and detection of a failure of the standard electrical supply.

8 Door (and internal elements) Foaming Area

DESCRIPTION:

The foaming area for the doors and internal elements should be arranged inside a new built separate safety box. At the inspection date the old box has been used for the door production with old production machines using CFC and had to be modified before startup of the new system. There should be one (moveable) new foaming head provided for the combined foaming of doors on one side and the internal elements on another side of the safety box. The door preheating device is a electrical heating system situated inside the old foaming box close to the foam injection area and is electrical connected by flexible plugs!

The door jigs are moved automatically with conveyors to the foaming and heating devices. The new installation in the safety box has not been complete. A documented time cycle of the production could not been provided.

The foaming of internal elements should be manual on a working bench with separate ventilation ducts.

REQUIREMENTS/DEVIATIONS:

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

a) The safety box is not complete erected.

Corrective action:

The safety box for the foaming area has to be erected. All accessible parts shall be of antistatic material. The floor shall be antistatic too (e.g. cement- or concrete floor, metal grating connected to grounding system, no electrostatic chargeable synthetic floor covering or sealing shall be used).

b) The gas detectors are not mounted.

Corrective action:

The position of the gas sensors has been discussed during the visit. They have to be mounted before commissioning.

c) The equipotential grounding system is not installed.

Corrective action:

All metal parts (e.g. grid, ventilation ducts, ...) are to be connected to a grounding system inside the safety box (spring-washers).

- d) The endangered area could not be clearly defined due to the missing time cycle of the foaming and heating process.

Corrective action:

A definition of the minimum time cycle for the foaming process has to be provided.

- e) There are non-explosion proofed flexible electrical plugs, an electrical preheating system and conveyor motors situated inside the safety box.

Corrective action:

All non-explosion proofed equipment has to be removed from the foaming area or electrically disconnected (cut off by failsafe timer system) during and 90 seconds after the foaming process.

- f) Several new devices are not installed (e.g. mixing head)

Corrective action:

All missing installation shall be completed before a final inspection.

- g) An ESD-switch and an escape route light close to the safety box door are missing.

Corrective action:

Mounting of the ESD-switch and connecting with the safety control panel. Mounting of the emergency route light (uninterruptible energy supply) and detection of a failure of the standard electrical supply.

9 General clauses

Referring to the latest information of UNIDO, all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

9.1 Electrical installation

- a) The general electrical supply of the new production equipment was not connected during inspection.

Corrective action:

Installation and connection of the main supply. Functional connection of the existing ESD-Switches to the new safety control panel.

- b) The mechanical protection for the electrical installation is not sufficient. Some parts of the old electrical equipment (e.g. cable glands) are damaged

Corrective action:

Laying of cables in trays; all cable trays should be closed. Repair of all existing damages in the existing installation.

9.2 Grounding system - potential bonding

- a) The grounding and potential bonding system is generally not sufficient.

Corrective action:

Connection of metal parts (e.g. skids of mixing units, storage tanks, ventilation ducts, control panels, piping, steel construction, cable trays, ...) to the earthing system.

Remark:

All connections in ex-zones have to be protected against loosening (by using spring-washer or tooth-washers).

10 Safety requirements during operation of the plant

10.1 Safety Instructions

Adequate training and instruction of the personal working with cyclopentane and isocyanate is a integral part of the plant safety. In a production process using flammable and poisonous liquids the following instructions for handling and training are a minimum safety requirement:

- Instructions for handling and storage of cyclopentane and isocyanate
- Instruction for the filling and periodic supervision of the C5 storage tank
- Working and safety instruction for the foaming process of the doors and cabinets
- Specification documents for the execution of periodic tests for safety relevant devices and functions and the calibration of the gas monitoring system. A test register has to be kept and stored for inspection visits.
- A fire alarm and emergency plan

10.2 Periodic Surveillance

An initial safety inspection covers the principal safety of the plant and the installation at the time of inspection (commissioning). To secure a safe operation for a lifetime period of the plant, the execution of periodic surveillance through an independent expert (third party) is an essential part of the safety concept.

The interval of the external surveillance is preferably one year. If the time between two surveillance inspections exceeds one year, the functional tests of safety systems and components have to be executed internal at least annual and must be properly documented.

The periodic surveillance inspections shall include all relevant systems, e. .g.:

- a check of the test register,
- the test of relevant safety functions and alarms,
- function tests of safety relevant components,
- the calibration of the gas monitoring system,
- a visual inspection of the properly condition and maintenance of the installation and equipment,
- a leakage (pressure) test for the C5-distribution piping

10.3 Preventive Maintenance

The minimum requirements for the preventive maintenance of the foaming units should be defined by the supplier (Cannon, Use and maintenance manual). For the locally supplied parts of the plant a internal guide including the necessary inspections and maintenance should be prepared by the company. It is recommended to document all maintenance works and inspections in a register.

11 Conclusions

The aim of the safety inspection visit of the refrigerator plant in Iran as mentioned in the contract and the „terms of reference“ was the execution of all necessary checks and tests in order to prepare a safety report for the plant. The safety inspection report, generally based on international standards, should guarantee the safe design and function of the converted plant.

A precondition for a positive inspection result is the completion of the whole installation and the preparation of all necessary supplies (electrical, liquids, gases).

At the time of the inspection visit many important installations have not been completed and no supply with electrical energy, cyclopentane, calibration gases and other necessary goods has been provided. Therefore the inspection has been carried out mainly as a consulting during erection and the not finished or missing installations/systems and the deviations at this project stage are stated in this report.

The correction of this deviations has been a necessary condition to achieve a positive inspection result.

A complicating condition has been the conversion (and combination) of the existing (and during inspection) still running old foaming equipment with the new cyclopentane foaming equipment. From the view of maintaining safety during all stages of the process, some additional measurements have been necessary (e. g. reconstruction of the conveyor system or timer cut off of all standard electrical systems close to the foaming area during the foaming process). This problems had to be solved before startup of the new plant!

Referring to the latest information of UNIDO (Dez. 2001), all points of the requirement lists have been corrected and inspected by the UNIDO Project Manager after completion of the converted plant.

Note: The TUV Austria takes no responsibility for results and declarations which have not been executed / inspected by the qualified personnel of the accredited inspection body.

12 Inspected Project Documentation

The provided documentation consists in general of the manuals, drawings and certificates of the supplier (Cannon). The only documentation obtained by the recipient company concerns the locally supplied storage tank.

12.1 Documentation of the Suppliers Equipment (Cannon)

12.1.1 Drawings

- General layout
- Air ducts, layout and detail

12.1.2 Manuals

- Premixing units - Use and maintenance manual
- Premixing units - Diagrams and spare parts
- Inspection book for accessories
- Mechanical manuals for accessories

12.2 Documentation of Movalled

- Cyclo-Pentan Tank Inspection Sheet by manufacturer (Shahin Dasht Amin Eng. Co.) about Leak Test (compressed air: 3,2 barG) and coating test

13 Standard List (international, european and national)

This list must not be complete but shall provide the reader of this report a sufficiently detailed information of the applicable regulations for the safety assessment.

In case there exists no adequate international standard for the review of a detailed requirement a basic risk assessment has been performed in order to achieve a practical solution.

- IEC 60079-14 Electrical apparatus for explosive gas atmospheres - Part 14: Electrical installations in hazardous areas (other than mines)
- IEC 60079-10 Electrical apparatus for explosive gas atmospheres - Part 10: Classification of hazardous areas
- EN 50014 Electrical apparatus for potentially explosive atmospheres - General requirements
- EN 50018 Electrical apparatus for potentially explosive atmospheres - Flameproof enclosures "d"
- EN 50019 Electrical apparatus for potentially explosive atmospheres - Increased safety "e"
- EN 50020 Electrical apparatus for potentially explosive atmospheres - Intrinsic safety "i"
- EN 50021 Electrical apparatus for potentially explosive atmospheres - Type of protection "n"
- EN 50039 Electrical apparatus for potentially explosive atmospheres - Intrinsic safety "i" Systems
- IEC 61024-1 Protection of structures against lightning - Part 1: General principles
- IEC/EN 60204-1 Safety of machinery - Electrical equipment of machines Part 1: General requirements
- TRbF 40 Petrol stations
- TRbF 100 General safety requirements
- TRbF 110 Stores
- TRbF 120 Stationary tanks of metallic and nonmetallic materials; general information
- ZH 1/8 Safety rules for requirements on the properties of stationary gas alarm systems for explosions protection
- ZH 1/10 Guidelines for the avoidance of dangers by explosive atmosphere including collection of examples - guidelines on protection against explosion (EX-RL)

- ZH 1/200
- VDMA 24169-1

Guidelines for avoiding the dangers of ignition due to electrostatic charges; guidelines "Static Electricity"

Air handling units; design-related explosion protection measures for fans; specifications for fans used to handle flammable gases, vapours or mist-containing atmospheres


TUV Austria
Division Electrical Engineering

Division Manager



Friedrich Bittermann

Safety Engineers:



Thomas Burger



Kurt Bruckner

This report may only be reproduced in its entirety and without any change.
A publication of its parts is permitted only with written authorization of TUV Austria.